

Sensitivity (ppb)	Element
5	Dy, Eu
5-50	In, Lu, Mn
50-500	Au, Ho, Ir, Re, Sm, W
500-5000	Ag, Ar, As, Br, Cl, Co, Cs, Cu, Er, Ga, Hf, I, La, Sb, Sc, Se, Ta, Tb, Th, Tm, U, V, Yb
$5000-5 \times 10^4$	Al, Ba, Cd, Ce, Cr, Hg, Kr, Gd, Ge, Mo, Na, Nd, Ni, Os, Pd, Rb, Rh, Ru, Sr, Te, Zn, Zr
$5 \times 10^4-5 \times 10^5$	Bi, Ca, K, Mg, P, Pt, Si, Sn, Ti, Tl, Xe, Y
$5 \times 10^5-5 \times 10^6$	F, Fe, Nb, Ne